

H.B.Stenzel, 208 East 33 street  
Austin, Texas

June 4. 1937

Aneroid

Mr. F.W.Bartlett

I have had a hard time deciding about the barometer mentioned in your letter of May 12. It appears to me that the model No. 5430 would hardly be very accurate, because the diameter of the dial is only three inches. This means that the parts of the interior mechanism are rather small. If it were possible to obtain delivery of the model No.5432 it would be the best. I am in hurry for the delivery, because I have not yet gotten to the stage in my work were I need elevations. Should model No.5432 be unobtainable, it be the next best thing to order a Paulin altimeter.

Please excuse my delay in this matter